

# Oil Field Environmental Incident Summary

**Incident:** 20140607233805

**Date/Time of Notice:** 06/07/2014 23:38

**Responsible Party:** Hess

**Well Operator:** HESS BAKKEN INVESTMENTS II, LLC

**Well Name:** BLDU DD-308

**Field Name:** BEAVER LODGE

**Well File #:** 14940

**Date Incident:** 6/7/2014

**Time Incident:** 10:46

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 155

**Rng:** 96

**Sec:** 5

**Qtr:** NE NE

**Location Description:** The spill was from a well site.

**Submitted By:** Brian Epperson

**Received By:**

**Contact Person:** Jason Henry  
3015 16th Street SW Suite 20  
Minot, ND 58701

**General Land Use:** Well/Facility Site

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Treater Popoff

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	30	Gallons	20	Gallons	0.71	barrels

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 7/17/2014

**Clean Up Concluded:** 6/13/2014

**Risk Evaluation:**

The well is shut and no immediate risks exists.

**Areal Extent:**

Estimated 30 gallons of emulsion with an impacted area of 60x130 off location to the south

**Potential Environmental Impacts:**

The impacted soil in the farm field will be excavated and disposed of at an approved landfill.

**Action Taken or Planned:**

A vac truck (PowerFuels) was dispatched to the site to vac up and free standing liquids.

**Wastes Disposal Location:** Clean Harbors

**Agencies Involved:****Updates**

---

**Date:** 6/9/2014    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release due to treater pressure release valve operation. Release sprayed off location. Followup is necessary.

---

**Date:** 6/18/2014    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Listed TWP-RNG-Sec is incorrect. Actually TWP-RNG-Sec is 155-96-2, Lat 48.283395 N Long - 102.979648 W

---

**Date:** 3/30/2015    **Status:** Inspection

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

3/30/2015 at 18:56, on location. Treater is in SW corner of wellpad. Wheat stubble field to south has been scraped to the southwest of the treater. No visible staining within or outside of scraped area.